



VSAT Required Tools & Equipment

- Cellular or Satellite phone
 - GPS unite with Latitude and Longitude readout
 - Spectrum Analyzer with LNB power feature or Perfect Vision Bird Dog USB Plus
 - Sighting compass (liquid filled)
 - Inclinator (magnetic base)
 - Bubble level
 - 25 ft. retractable tape measure
 - Rugged Laptop with Windows 2K/XP or higher, with LAN port, RS232 port, iSite software version applicable for iDirect Hub firmware (contact FTI prior to install)
 - Ethernet Cables: 1 crossover, 1 straight through
 - Tool Kit: Allen wrenches, short Philips screwdriver, regular Philips & Flathead screwdriver, metric/SAE sockets, $\frac{3}{8}$ " and $\frac{1}{2}$ " Hex drivers (ratchets), drill & bits, hammer, $\frac{1}{2}$ " wrench, $\frac{9}{16}$ " wrench, $\frac{3}{8}$ " wrench, (2) $\frac{3}{4}$ " wrenches, and (2) $\frac{15}{16}$ " wrenches
 - Digital Voltmeter
 - Stripper for RG6/RG11 cable
 - Crimp tool for RG6/RG11 cable and connectors
 - RG6 test cables (2-10' lengths)
 - Expendables: electrical tape, silicon grease, RTV sealant, UV rated black cable ties (assorted sizes), touch up paint,
-

Complete Installation Kits available for Sale

Pease contact the FTI sales department at:

sales@ftionline.com

800-833-3353